

## 8. POPULAR ALL PURPOSE THERMOMETERS

### ITE-8031

### DIGITAL THERMOMETER With °C or °F selection

#### FEATURES

- Measurement range: **-50°C - 1300°C** (-50°F - 1999°F).
- Type **'K'** thermocouple.
- Operating temperature and humidity:  
**0°C to 50°C** (32°F to 122°F), 0 % - 80 % RH.
- Storage temperature and humidity:  
**-10°C to 60°C** (14°F to 140°F), 0 % - 70 % RH.
- Data Hold function.
- T1 & T2 dual points display.
- T1 - T2 differential measurement.
- 9 V battery included.

