

GASKETS, RED COPPER FLARE
*(Put in between brass or
to steel or to copper for high sealing)*

B2-03	For $\frac{3}{16}$ " flare
B2-04	For $\frac{1}{4}$ " flare
B2-05	For $\frac{5}{16}$ " flare
B2-06	For $\frac{3}{8}$ " flare
B2-08	For $\frac{1}{2}$ " flare
B2-10	For $\frac{5}{8}$ " flare
B2-12	For $\frac{3}{4}$ " flare

