


**PRT-8020 PHASE ROTATION TESTER**

**FEATURES**

- Shows the correct way to make 3 phase connections and prevents as such costly damage.
- Saves time, no need to disconnect drive shaft couplings.
- Identifies open windings.
- Visual as well as audible phase rotation indication.
- Low battery indicator (insufficient battery power will lead to faulty testing).
- Electrical safety : Double insulated IEC/EN 61010-1 CAT III / 600 V / CE.
- Reliable solid state components.
- Alligator test clips open 12 mm (1/2") to fit most terminals.
- Shirt pocket size.

**SPECIFICATIONS**

- Signal input voltage: 50 V AC to 500 V AC overload protection till 750 V AC.
- Signal input frequency: 45 Hz to 65 Hz.
- Operating temperature: **0°C to +40°C**.
- Operating humidity: less than 80 % relative humidity.
- Power supply: 9 V battery included.
- Dimensions: **85 mm x 50 mm x 20 mm** (height x width x depth).
- Weight: **210 g** including battery.
- Accessories included: 200 cm test leads with alligator test clips, instruction manual, vinyl pouch.



PRT-8020