

COUDES à 45°

CODE	Connexions d	± Dimensions (mm)		
		a	b	Z
5040-06	06 mm	9	11	3
5040-08	08 mm	11	13	4
5040-10	10 mm	12	14	4
5040-12	12 mm	14	16	5
5040-14	14 mm	16,5	16,5	5,5
5040-15	15 mm	17	19	6
5040-16	16 mm	18	20	7
5040-18	18 mm	20	22	7
5040-22	22 mm	25	27	9
5040-28	28 mm	29	31	10
5040-35	35 mm	37	39	14
5040-42	42 mm	42	44	15
5040-54	54 mm	52	54	20
5040-64	64 mm	62	65	27
5040-67	67 mm	65	68	28,5
5040-76	76 mm	68	71	32
5040-80	80 mm	83	85	48
5040-89	89 mm	78	81	37,5
5040-108	108 mm	110	113	60
5040-133	133 mm	280	280	235

